

**875—95.8(89) Carbonization.** Carbonization and other indications of improper flame shall be corrected through adjusting and cleaning the burners in accordance with the manufacturer's recommendations.